

R
O
L
L

1

P
H
O
T
O

1



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95

Direction: West **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0840

Subject: Area in front of the facility (on the south side of the property) looking west with the Harcros facility in the background.

R
O
L
L

1

P
H
O
T
O

2



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** None **Date:** 6/27/95

Direction: West-northwest **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0840

Subject: View of the property looking west-northwest. The large tank at the right side of the photo is the former #5 diesel fuel tank.

RCRA 6/27/1995



132587

R
O
L
L

1

P
H
O
T
O

3




Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** None **Date:** 6/27/95
Direction: North-northwest **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0840
Subject: View of the property showing the #5 diesel fuel tank at the left and the former laboratory/office building at the right (white cinder block building).

R
O
L
L

1

P
H
O
T
O

4



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** None **Date:** 6/27/95
Direction: North **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0840
Subject: View of the property facing north with a portion of the former laboratory/office building at the left and a portion of the former DAITOM building at the right.



ROLL 1 PHOTO 5

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: None

Date: 6/27/95

Direction: North-northeast

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0840

Subject: View of the former DAITOM building.

R
O
L
L

1

P
H
O
T
O

6



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: None

Date: 6/27/95

Direction: East-northeast

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0841

Subject: View of the property facing east-northeast with a portion of the former DAITOM building at the left and the Postal Bulk Mail Center in the background at the right.

R
O
L
L

1

P
H
O
T
O

7



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: None

Date: 6/27/95

Direction: East

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0841

Subject: View of the property facing east with the Postal Bulk Mail Center in the background. Note the piles of material stacked along the fence.

R
O
L
L

1

P
H
O
T
O

8



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: None

Date: 6/27/95

Direction: South-southeast

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0841


Subject: Material located along the south fence in front of the former DAITOM plant.

R
O
L
L

1

P
H
O
T
O

9



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: None

Date: 6/27/95

Direction: Southeast

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0845

Subject: View of the southeast corner of the former lab room. Note the miscellaneous equipment and scrap/salvaged material.

R
O
L
L

1

P
H
O
T
O

10



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** None **Date:** 6/27/95
Direction: Southwest **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0845
Subject: View of the southwest corner of the former lab room. Note the bottles in the southwest corner.

R
O
L
L

1

P
H
O
T
O

11



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: South **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0847
Subject: Picture of the desk in the southwest corner of the former lab room. Note the five bottles which are labeled as laquer thinner and paint thinner. The third bottle has a skull and crossbones drawn on it.

R
O
L
L

1

P
H
O
T
O

12



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** None **Date:** 6/27/95
Direction: West **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0848
Subject: Looking at the desk just inside the west side of the north doorway to the former lab. Note the three containers of Weedar 64A which contains Herbicide 2, 4-D amine .

R
O
L
L

1

P
H
O
T
O

13



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: South **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0850
Subject: View of the former ladies bathroom depicting scrap/salvaged material in the southwest corner.

R
O
L
L

1

P
H
O
T
O

14



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: Southeast

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0853

Subject: View of the southeast wall of the former tech room depicting the general condition of the room.



ROLL 1 PHOTO 15

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0855

Subject: View of the boiler room in the former laboratory/office building. Note miscellaneous containers of paints, solvents, and other materials.



ROLL 1 PHOTO 16

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: North

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0857

Subject: View of the former breakroom area. Note the water damage to the floor and walls.

R
O
L
L

1

P
H
O
T
O

17



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: Southwest

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0901

Subject: View of miscellaneous scrap/salvage material located in the former mens bathroom.



ROLL 1 PHOTO 18

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: None

Date: 6/27/95

Direction: West

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0902

Subject: View of the west-side office exit.
Note the two compressed gas tanks. One is labeled acetylene, the other oxygen.

R
O
L
L

1

P
H
O
T
O

19



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: East **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0905
Subject: View of the chemical/product pipe rack leading into the DAITOM plant. Photo was taken from the north side of the laboratory/office building. Notice the old air conditioning units in the left side of the photo.

R
O
L
L

1

P
H
O
T
O

20




Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: North **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0910
Subject: View of the former DAITOM plant production area. Note the miscellaneous scrap/salvage material.

R
O
L
L

1

P
H
O
T
O

21



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: Up **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0910
Subject: View of openings in the ceiling (1st floor) that formerly housed methanol tanks and associated piping.

R
O
L
L

1

P
H
O
T
O

22



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: Up **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0914
Subject: View of opening in the ceiling (1st floor) that housed methanol tanks and associated piping.

R
O
L
L

1

P
H
O
T
O

23



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: North

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0917

Subject: View of the former reactor room. Note scrap tires, light bulbs, and miscellaneous scrap/salvage material. Also note the drain to the left.

R
O
L
L

1

P
H
O
T
O

24



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0918

Subject: View of the drain in the northeast corner of the reactor room.

R
O
L
L

1

P
H
O
T
O

25



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: Northwest **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0922
Subject: View of miscellaneous scrap/salvage material in northwest corner of reactor room. Note numerous paint and solvent cans.

R
O
L
L

1

P
H
O
T
O

26




Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0925
Subject: View of possible support for former tanks (between fire extinguisher and white 5-gallon bucket).

R
O
L
L

1

P
H
O
T
O

27



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0927


Subject: View of openings in the ceiling that housed tanks (1st floor).

R
O
L
L

1

P
H
O
T
O

28



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0928


Subject: View of two additional, smaller openings in ceiling that formerly housed tanks (1st floor).

R
O
L
L

1

P
H
O
T
O

29



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0931
Subject: View of a large opening in ceiling that formerly housed tanks.

R
O
L
L

1

P
H
O
T
O

30



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0932
Subject: Photo of the floor drain in what was described as the former welding booth located in the southeast corner of the first floor of the former DAITOM plant.



ROLL 1 PHOTO 31

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: North

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0935

Subject: View of the drain in the northwest corner of the northeastern section of the first floor of the DAITOM plant.

R
O
L
L

1

P
H
O
T
O

32




Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0943
Subject: View of openings in the ceiling of the second floor which formerly housed tanks.

R
O
L
L

1

P
H
O
T
O

33



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: North **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0945
Subject: View of the former cyanide storage area located inside the cage.

R
O
L
L

1

P
H
O
T
O

34



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0945

Subject: View of the drain inside the former cyanide storage area.



ROLL 1 PHOTO 35

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: Southeast

Camera Type: Fuji 35m m

Film Type: 200 A SA

Time: 0945

Subject: View of opening in floor where a cyanide reactor was formerly housed. Note the white build-up on the floor and the pipes.



ROLL 1 PHOTO 36

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0946

Subject: View of opening in floor where a cyanide reactor was formerly housed. Note the white build-up on the floor and the pipes.

R
O
L
L

1

P
H
O
T
O

37



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0948
Subject: View of the piping in the former sodium cyanide room. Note the white build-up on the I-beams and piping.

R
O
L
L

2

P
H
O
T
O

1



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: West **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 0950
Subject: View of the third floor looking west. Note white build-up on pipes.

R
O
L
L

2

P
H
O
T
O

2



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0952

Subject: View of the white build-up on the pipes (third floor).

R
O
L
L

2

P
H
O
T
O

3



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 0955

Subject: View of the floor drain on the third floor.

R
O
L
L

2

P
H
O
T
O

4



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: None

Date: 6/27/95

Direction: North

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1000

Subject: View from the roof of the former surface impoundment (surface impoundment is between the trees and the fence in the center of the photo).

R
O
L
L

2

P
H
O
T
O

5



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: None

Date: 6/27/95

Direction: Northeast

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1000

Subject: View of the former surface impoundment from the roof looking northeast.



ROLL 2 PHOTO 6

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: None

Date: 6/27/95

Direction: West

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1005

Subject: A view from the roof, showing the laboratory/office building (lower portion of photo), former THAN parking lot (center of the photo), and Harcos (in the top of the photo).

R
O
L
L

2

P
H
O
T
O

7




Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** None **Date:** 6/27/95
Direction: Northwest **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1005
Subject: View of the #5 diesel fuel tank and former boiler building in the center of the photo, Harcros facility in the background.

R
O
L
L

2

P
H
O
T
O

8




Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1015
Subject: DAITOM Flow Chart found in plant manager's office

R
O
L
L

2

P
H
O
T
O

9



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS Photographer: Jeffery Robichaud Witness: James Aycock Date: 6/27/95
Direction: N/A Camera Type: Fuji 35mm Film Type: 200 ASA Time: 1017
Subject: DAITOM flow chart

R
O
L
L

2

P
H
O
T
O

10



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS Photographer: Jeffery Robichaud Witness: James Aycock Date: 6/27/95
Direction: Southwest Camera Type: Fuji 35mm Film Type: 200 ASA Time: 1020
Subject: View of the west side of the 2nd floor.

R
O
L
L
2
P
H
O
T
O
11



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1025
Subject: View of an opening in the second floor that formerly held an unknown process tank.

R
O
L
L
2
P
H
O
T
O
12



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: East **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1028
Subject: View of writing on wall that identifies that this portion of the building formerly contained a process involving acrylonitrile.



ROLL 2 PHOTO 13

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: Northeast

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1031

Subject: View of the piping in the former reactor room located on the second floor.

R
O
L
L

2

P
H
O
T
O

14



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1032
Subject: View of the floor drain located in the former reactor room on the second floor.

R
O
L
L

2

P
H
O
T
O

15



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1035
Subject: View of the floor drain located in the southeast corner of a room on the west side of the second floor.

R
O
L
L

2

P
H
O
T
O

16



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: South **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1045
Subject: View of unknown pipes leading into/out of the northwest corner of the former DAITOM plant.

R
O
L
L

2

P
H
O
T
O

17



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: Southwest **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1050
Subject: View of a former tank control pad located to the north of the lab building.

R
O
L
L

2

P
H
O
T
O

18



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: East

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1051

Subject: View of the former Brine, Freon, and Mehanol tank location (North of the lab building).



ROLL 2 PHOTO 19

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1053

Subject: View of a corroded drum of what appeared to be solid or dried paint to north of the former Brine, Freon, and Methanol pad. Note streaks on the side of the drum and dark spots near the top of drum which are holes. Appears to be stressed vegetation in proximity of drum.

R
O
L
L

2

P
H
O
T
O

20



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: South **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1055
Subject: View of the former Brine, Freon and Methanol pad taken from top of its containment wall. Note staining on the floor of the pad.

R
O
L
L

2

P
H
O
T
O

21



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: North **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1056
Subject: View of the north side of containment wall for the former Brine, Freon, and Methanol pad. Note the two 5-gallon pails. Unknown contents.

R
O
L
L

2

P
H
O
T
O

22



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: North **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1059
Subject: View of the concrete pad where a liquid nitrogen tank was formerly located. Note the miscellaneous scrap/salvage material located on the pad.

R
O
L
L

2

P
H
O
T
O

23



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: North **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1100
Subject: View of the concrete saddle where an LP gas tank was formerly located (One saddle is to the left in the photo, the other is to the right).

R
O
L
L

2

P
H
O
T
O

24



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: East **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1103
Subject: View of the concrete pad where an Hydrochloric Acid (HCl) tank was formerly stored (Foreground).

R
O
L
L

2

P
H
O
T
O

25



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: East **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1108
Subject: View of the concrete pad to the east of HCl pad. Formerly housed eight raw materials storage tanks.
Note the pile of paper and debris in the northeast corner of the pad.

R
O
L
L

2

P
H
O
T
O

26



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95

Direction: West **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1110

Subject: A pile of debris at the southeast corner of concrete pad which formerly housed eight raw materials storage tanks. Note the two corroded cans which may have contained solvent.

R
O
L
L

2

P
H
O
T
O

27



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95

Direction: North **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1115

Subject: View of a battery on northeast corner of the containment wall which formerly housed the eight raw materials tanks. Notice the discoloration on the wall underneath the battery.



ROLL 2 PHOTO 28

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1118

Subject: View of a corroded 55-gallon drum of unknown contents with a one-gallon paint can in front and several quart paint cans that contained orange and yellow paint on top. The one-gallon and quart cans were leaking.



ROLL 2 PHOTO 29

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1119

Subject: A close-up of camouflage paint cans at the base of the 55-gallon drum, hidden in the foliage.



ROLL 2 PHOTO 30

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1122

Subject: View of the area north of the rear of the former DAITOM building. Note the six compressed gas tanks at the right center of the photo. All are labeled Thomas Hayward and have green tops. They appear to be empty.



ROLL 2 PHOTO 31

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: East

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1126

Subject: A photo of a group of batteries on the paved area north of the rear of the former DAITOM plant. Note the trail of discoloration that leads away from the batteries and leaves the pad next to the blue object at the top of the photo entering the area with foliage.

R
O
L
L

2

P
H
O
T
O

32



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1131
Subject: A photo of a dark liquid seep located in the soil four feet from the end of the asphalt road which runs in between the former laboratory/office building and the former boiler building.

R
O
L
L

2

P
H
O
T
O

33



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: South **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1135
Subject: A photo of soil discoloration near the end of the asphalt road located between the former laboratory/office building and the former boiler building.



ROLL 2 PHOTO 34

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1139

Subject: A photo of the remnants of a metal container (in the center of the photo) located near the dark liquid seep. Size of the container is unknown.

R
O
L
L

2

P
H
O
T
O

35



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: North **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1140
Subject: View of the concrete pad where an ethyl acetate tank was formerly located.

R
O
L
L

1

P
H
O
T
O

36



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: South **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1151
Subject: View of the concrete pad where a methanol tank was formerly stored.

R
O
L
L

2

P
H
O
T
O

37



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1155

Subject: View of the pad where a cyanide destruction unit was formerly located.

R
O
L
L

3

P
H
O
T
O

1



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: Northeast

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1320

Subject: View of the inside of the northeast corner of the former boiler building. Note the miscellaneous scrap/salvage material.

R
O
L
L

3

P
H
O
T
O

2



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: Northwest **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1321
Subject: View of the inside of the northwest corner of the former boiler building. Note the miscellaneous scrap/salvage material.

R
O
L
L

3

P
H
O
T
O

3



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: North **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1321
Subject: View of the south side of the former boiler building.

R
O
L
L

3

P
H
O
T
O

4



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: North

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1325

Subject: Lift station located to the north of the former boiler building



ROLL 3 PHOTO 5

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1327

Subject: Lift Station and pump control panel located to the north of the former boiler building.

R
O
L
L

3

P
H
O
T
O

6



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1328

Subject: View of the inside portion of the lift station.

R
O
L
L

3

P
H
O
T
O

7



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: East

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1342

Subject: The former THAN surface impoundment (left side of the photo) is behind the fence. Note drums in the southwest corner. They appeared to be empty, however several of the drums had burst open and may have released their contents to the soil.

R
O
L
L

3

P
H
O
T
O

8



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: East

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1343

Subject: View of the former THAN surface impoundment (the area behind the fence).

R
O
L
L

3

P
H
O
T
O

9



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: Northeast

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1343

Subject: The former THAN surface impoundment (the area behind the fence). Note the monitoring well in the foreground (far right side of the photo).

R
O
L
L

3

P
H
O
T
O

10



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95

Direction: North **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1352

Subject: The former THAN surface impoundment. Note monitoring well in the foreground.

R
O
L
L

3

P
H
O
T
O

11



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95

Direction: Northwest **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1353

Subject: The former THAN surface impoundment from the northeast corner of the DAITOM property.



ROLL 3 PHOTO 12

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1402

Subject: Containers of used oil and paint cans to the north of the former DAITOM plant.



ROLL 3 PHOTO 14

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1415

Subject: A crack in the northeast corner of the secondary containment berm around the former ethyl acetate recovery pad.

R
O
L
L

3

P
H
O
T
O

15



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95

Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1419

Subject: A crack in south side of the secondary containment berm around the former methanol recovery pad.

R
O
L
L

3

P
H
O
T
O

13



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1405

Subject: Three drums of unknown material located to the north of the former DAITOM plant adjacent to a electric transformer.



ROLL 3 PHOTO 16

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: Southeast

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1421

Subject: Discoloration on the former ethyl acetate pad which appears to head towards the drain with no grate in the southeast corner.



ROLL 3 PHOTO 17

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1428

Subject: A hole in ground between former cyanide destruction unit and the former ethyl acetate recovery pad. Pipes are seen leading from the former cyanide destruction unit into the hole. The pipe reportedly connected to the facility sanitary sewer system.



ROLL 3 PHOTO 18

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1429

Subject: Discolored concrete located near the southwest corner of the former cyanide destruction unit pad.

R
O
L
L

3

P
H
O
T
O

19



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1432
Subject: The secondary containment drain (left side of the photo) located near the northeast corner of the former cyanide destruction unit pad.

R
O
L
L

3

P
H
O
T
O

20



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: South **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1440
Subject: Loading dock area behind the former DAITOM plant. Note the salvage/scrap material piled around the building.

R
O
L
L

3

P
H
O
T
O

21



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: West **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1443
Subject: A concrete pad or underground vault (tank) northeast of the former DAITOM plant.

R
O
L
L

3

P
H
O
T
O

22



Facility: Thomas Hayward Agriculture & Nutrition
Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95
Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1444
Subject: Open manhole cover in the concrete pad or vault (tank) located to the northeast of the former DAITOM plant. Note the tank or vault was full of water.



ROLL 3 PHOTO 25

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1459

Subject: Black substance staining the soil and vegetation between the #5 diesel fuel tank and the former boiler building. The substance was leaking from an overhead pipeline leading from the #5 diesel fuel tank to the former boiler building.

R
O
L
L
3
P
H
O
T
O
23



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95

Direction: South **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1444

Subject: Two concrete pads located northeast of the former DAITOM plant. Photo taken from pad in photo 21, 22.



ROLL 3 PHOTO 24

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1458

Subject: Black substance below the pipes (northwest side of the tank) leading into/out of the #5 diesel fuel tank.

R
O
L
L

4

P
H
O
T
O

1



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95

Direction: Northwest **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1505

Subject: #5 diesel fuel tank and the former boiler building (at the right side of the photo) and a sump or drain in the foreground. The sump was utilized for catching leaks during railcar/truck off-loading or loading products or materials.



ROLL 4 PHOTO 2

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1506

Subject: View of the sump or drain on east side of the railcar/truck loading/unloading area located between the former laboratory/office building and #5 diesel fuel tank.

R
O
L
L

4

P
H
O
T
O

3



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: Southwest

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1508

Subject: Used oil stain at southwest corner of the road between the former laboratory/office building and the former boiler building..

R
O
L
L

4

P
H
O
T
O

4



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: Southeast

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1515

Subject: Southeast corner of the parking lot located west of the former laboratory/office building. Note the crack in the asphalt and the used oil stain in the center of the photo.



ROLL 4 PHOTO 5

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: East

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1518

Subject: Discoloration (appeared to be used oil) located along the south edge of parking lot west of the former laboratory/office building.



ROLL 4 PHOTO 6

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: South

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1518

Subject: Crack in parking lot (south center portion of the parking lot). Note the crack appears to be stained with used oil.



ROLL 4 PHOTO 7

Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: West

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1522

Subject: Stained asphalt in the middle of the south side of the parking lot located west of the former laboratory/office building.

R
O
L
L

4

P
H
O
T
O

8



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: Southwest

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1527

Subject: Scrap/salvaged air conditioning units located near the south side of the parking lot west of the former laboratory/office building. Note: Capacitors had not been removed from the air conditioning units.

R
O
L
L

4

P
H
O
T
O

9



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS

Photographer: Jeffery Robichaud

Witness: James Aycock

Date: 6/27/95

Direction: N/A

Camera Type: Fuji 35mm

Film Type: 200 ASA

Time: 1529

Subject: A pile of electric capacitors (30-40 capacitors) located in the middle of the parking lot west of the former laboratory/office building.

R
O
L
L
4
P
H
O
T
O
10



Facility: Thomas Hayward Agriculture & Nutrition

Location: Kansas City, KS **Photographer:** Jeffery Robichaud **Witness:** James Aycock **Date:** 6/27/95

Direction: N/A **Camera Type:** Fuji 35mm **Film Type:** 200 ASA **Time:** 1530

Subject: A close-up of the three different capacitors found in the pile in the middle of the parking lot, west of the former laboratory/office building.